

IMMEDIATE ACTION

SERVICE



BULLETIN

NUMBER 4

Rev. Date: 2-15-46

SUBJECT: Maintenance of Fuel System

MODELS AFFECTED: All Models Manufactured up to and including
December, 1945

As a safety precaution, it should be noted that the drain fitting in the bottom of the gasoline tank has a bronze or copper wire cloth screen soldered into the brass bushing which is screwed into the fitting on the tank.

It is highly advisable to remove this brass assembly and clean off all accumulations of foreign matter at intervals of each one hundred hours of flight. With the assembly removed, the tank should be thoroughly flushed with gasoline to rinse out any sediment which may have lodged in the tank.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.