

IMMEDIATE ACTION

SERVICE



BULLETIN

NUMBER 21

Aug. 21, 1939

Rev. Date: 2-18-46

SUBJECT: Engine Mounting Bolt Failures

MODELS AFFECTED: J3C-65 Cubs With Continental A50 Engine Installation

We have been informed recently that several cases of failure of the bolts which attach the Continental A50 engine to the engine mount have been noted. It appears, therefore, that these bolts should be inspected at every line inspection of the airplane and, if any change in the "feel" of the vibration characteristics of the engine is noted, the bolts should be inspected immediately.

If you have had a bolt failure or if your engine-propeller combination appears to be excessively rough, we would suggest installing another propeller of the proper power and speed rating to try to obtain smoother engine operation.

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.