IMMEDIATE ACTION





BULLETIN

October 15, 1945 Rev. Date: 2-20-46

SUBJECT: Windshield Replacement

MODELS AFFECTED: J3 Series Airplanes With Formed Eyebrow Fairing Tubes

In order to install a one-piece plexiglas windshield the following procedure is recommended:

- 1. Remove old windshield (4, Figure 1), eyebrow fairings (2, 3, Figure 1), and top center fairing (1, Figure 1).
 - 2. Remove old windshield attachment tabs (5, Figure 1) from fuselage cowl.
- 3. Place new one-piece windshield, part number 10009-00, in position and attach at left and right sides. (See Figure 2.) On left side use new trimstrip, part number 53922-17, and attach with five (5) No. $6-32 \times 1/2$ " machine screws and elastic stop nuts using old holes in superstructure.

NOTE: 1/4" holes should be used in the windshield at these attachments to allow for expansion and contraction of the windshield material. Maintain a minimum edge distance of 1/4". Drill holes carefully to prevent cracking of windshield.

Make same attachment on right side using new trimstrip, part number 54132-00.


- 4. Replace old top center fairing (1, Figure 1) and attach to windshield with three (3) No. $6-32 \times 1/2$ " machine screws and elastic stop nuts. (1/4" holes in windshield). Use washers, part number 54161-00 and 85012-28, as shown in Figure 2.
- 5. Place attachment collar, part number 23942-00, in position and attach to fuselage cowl with eighteen (18) No. 6-32 x 3/8" machine screws and elastic stop nuts as shown in Figure 2. Place rubber beading No. 81511-10 over bottom edge of windshield to seal this attachment.

NUMBER 76

6. Fit eyebrow fairings, part numbers 60803-00 and 60803-01, in position (trim if necessary) and attach to top rear edge with two (2) No. 4-36 x 3/8" machine screws, washer, part number 85012-13, and Tinnerman nut. Attach to butt rib capstrip with five (5) No. 4 Parker screws. Place rubber beading, part number 81511-06, under edge of fairing where it contacts the windshield.

NOTE: Soap and water is recommended to clean this windshield.

All material required to accomplish this windshield replacement can be obtained through your local dealer or distributor.



SERVICE BULLETIN NO. 76

