

IMMEDIATE ACTION

SERVICE

NUMBER 85




BULLETIN

April 25, 1946

SUBJECT: REWORKING OF BOTTOM COWL FOR REPLACING AIR SCOOP
EQ5259 WITH EQ5370 (CONTINENTAL PART NUMBERS)

MODELS AFFECTED: J3C AIRPLANES

When replacing the vertical faced filter air scoop (Part No. EQ5259) with the new slant faced filter air scoop (Part No. EQ5370), the bottom cowl assembly will have to be reworked as per sketch below.



PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.