

Stinson Service Bulletins and Letters

Bulletins and Letters by Subject

[Stinson SB&L Index.doc](#)

108 Conversion to 108-1 or 108-2	S.L. 73A	
Accident Reports	S.L. 53	
Aeromatic Propeller Adjustment	S.B. 262	
Air Filter - Cleaning & Carburetor Hot Air	S.L. 66	
Aircraft Nameplate change	S.B. 261	
Ash Tray Cover	S.B. 246	
Battery and Battery Box Care	S.L. 71	
Battery eligibility for 108 Series	S.L. 81	
Battery Vent Tube Relocation	S.B. 259	
Blind Rivets for Field Repairs	S.L. 18	
Cabin Sliding Window Inspection	S.B. 253	
Carb Accelerator Pump Kit, A666-581	S.B. 255	
Compass Deviation	S.L. 40	
Control Surface Bearing Replacement	S.L. 76	
Control Wheel Modification	S.B. 249	
Dome Light Lens and Radio Grill Removal	S.L. 48	
Elevator Trim Tab Control Horn	S.B. 257	
Field Refinishing Procedure	S.L. 58	
Float Fitting Kit List	S.B. 264	
Franklin 165 Installation on 108 & 108-1	S.L. 74A	
Fuel Cap Orientation	S.L. 78	
Fuel Gauge Modification	S.B. 251	
Fuel Seepage Into Cabin	S.B. 267	
Fuel Selector Valve Indexing	S.L. 77	
Fuel Valve, Replacement of Click Washer	S.B. 250	
Jettison Doors	S.B. 263	
Leakage-Cabin Door Windows	S.B. 247	
Metal Spar Splice Kits	S.L. 208	
Mixture Control - Leaning for performance	S.L. 64	
Oleo Shock Plunger Rework	S.L. 75	
Operating Limitations Placard	S.L. 79	
Radio Use when starting engine	S.L. 60	
Rudder Bungee Kit List	S.B. 265	
Rudder Cable Inspection	S.B. 266	
Rudder Cable, two forward Misalignment	S.B. 260	
Rudder Skins, Repair or reinforcement at hinge	S.B. 258	
Seaplane Operations	S.L. 70	
Stabilizer Leading Edge Attachment Insp.	S.B. 254	
Tailwheel Installation	S.B. 252	
Tinnerman Nuts	S.L. 56	
Wiring Harness Protection	S.B. 248-A	

Bulletins and Letters by Number

S.L. 18	Blind Rivets for Field Repairs	
S.L. 40	Compass Deviation	
S.L. 48	Dome Light Lens and Radio Grill Removal	
S.L. 53	Accident Reports	
S.L. 56	Tinnerman Nuts	
S.L. 58	Field Refinishing Procedure	
S.L. 60	Radio Use when starting engine	
S.L. 64	Mixture Control - Leaning for performance	
S.L. 66	Air Filter - Cleaning & Carburetor Hot Air	
S.L. 70	Seaplane Operations	
S.L. 71	Battery and Battery Box Care	
S.L. 73A	108 Conversion to 108-1 or 108-2	
S.L. 74A	Franklin 165 Installation on 108 & 108-1	
S.L. 75	Oleo Shock Plunger Rework	
S.L. 76	Control Surface Bearing Replacement	
S.L. 77	Fuel Selector Valve Indexing	
S.L. 78	Fuel Cap Orientation	
S.L. 79	Operating Limitations Placard	
S.L. 81	Battery eligibility for 108 Series	
S.L. 208	Metal Spar Splice Kits	
S.B. 246	Ash Tray Cover	
S.B. 247	Leakage-Cabin Door Windows	
S.B. 248-A	Wiring Harness Protection	
S.B. 249	Control Wheel Modification	
S.B. 250	Fuel Valve, Replacement of Click Washer	
S.B. 251	Fuel Valve, Replacement of Click Washer	
S.B. 252	Fuel Gauge Modification	
S.B. 253	Tailwheel Installation	
S.B. 254	Cabin Sliding Window Inspection	
S.B. 255	Stabilizer Leading Edge Attachment Insp.	
S.B. 257	Carb Accelerator Pump Kit, A666-581	
S.B. 258	Elevator Trim Tab Control Horn	
S.B. 259	Rudder Skins, Repair or reinforcement at hinge	
S.B. 260	Battery Vent Tube Relocation	
S.B. 261	Rudder Cable, two forward Misalignment	
S.B. 262	Aircraft Nameplate change	
S.B. 263	Aeromatic Propeller Adjustment	
S.B. 264	Jettison Doors	
S.B. 265	Float Fitting Kit List	
S.B. 266	Rudder Bungee Kit List	
S.B. 267	Rudder Cable Inspection	